



NEW TRASDATA (JTAG/BDM/BOOT) ECU APPLICATION LIST

Release A/15 (02/01/2015) referred to SW: 3.0.126 DLL: 1.0.127 FW: 6.067 build 0001

DIMSPORT Srl Località San Torio 8B, Zona Industriale Madonnina 15020 Serralunga di Crea (AL) ITALY T +3901429552 F +390142940094

http://www.dimsport.it sales dept: info.race@dimsport.it; tech dept: support.race@dimsport.it

This application list is merely indicative. Dimsport Srl reserves the right to modify the list without any notice and at any time.

La presente lista ha carattere meramente indicativo. Dimsport Srl si riserva il diritto di apportare modifiche in qualunque momento e senza preavviso.

CPU SUPPORTED (GROUPS AND FAMILIES) / CPU SUPPORTATE (GRUPPI E SOTTOFAMIGLIE)

GROUP ID	CPU GROUP / GRUPPO CPU	CPU FAMILIES INCLUDED IN THE GROUP / FAMIGLIE CPU INCLUSE NEL GRUPPO
TF001	MOTOROLA MPC55X/MPC56X CPU group	-> 01 - MOTOROLA MPC55X/MPC56X (TM001)
TF002	STMICROELECTRONICS ST10 CPU group	-> 02 - STMICROELECTRONICS ST10 (TM002) -> 05 - SPECIAL ST10 (TM005)
TF003	INFINEON TRICORE CPU group	-> 03 - INFINEON TRICORE NO PSW (TM003) -> 04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004) -> 11 - INFINEON TRICORE SIEMENS SD16 PORSCHE (TM011) -> 12 - INFINEON TRICORE BOSCH EDC17 TPROT8 BMW (TM012) -> 13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013) -> 14 - INFINEON TRICORE NO PSW KLINE (TM014) -> 15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAL (TM015) -> 16 - INFINEON TRICORE FOMOCO SID208/SID807 (TM016) -> 18 - INFINEON TRICORE SIEMENS PCR2.1/SIMOS8.xx VAG (TM018) -> 19 - INFINEON TRICORE BOSCH MEDC17 TPROT11 KIA/HYUNDAI -> 20 - INFINEON TRICORE BOSCH MEDC17 TPROT12 FORD -> 22 - INFINEON TRICORE BOSCH EDC17 GPT BMW
TF004	MOTOROLA MPC55XX CPU group	-> 06 - NEXUS MOTOROLA MPC55XX (TM006)
TF005	RENESAS SH7050 CPU group	-> 07 - RENESAS SH7050 (TM007)
TF006	MITSUBISHI MH7xxx/MH8xxxx CPU group	-> 08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)
TF007	MOTOROLA MC68xxx CPU group	-> 09 - MOTOROLA MC68xxx (TM009)
TF008	MOTOROLA HC12 CPU group	-> 10 - MOTOROLA HC12 (TM010)
TF009	RENESAS M32R CPU group	-> 17 - RENESAS M32R (TM017)

ECU SUPPORTED / CENTRALINE SUPPORTATE

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDDII PATCH / SBLOCCO OBDDII
595	All - Tutti	Recon	CM554	MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)	
615	All - Tutti	Bosch	EDC17 CV41	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)	
614	All - Tutti	Bosch	EDC17 CV42	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)	
383	Agrale Cargo Truck	Bosch	EDC17 C1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
545	Agrale Cargo Truck	Bosch	EDC17UC31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
94	Aprilia / Piaggio	IAW Marelli	5DM	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
239	Aprilia / Piaggio	IAW Marelli	75M	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
424	Aston Martin	FoMoCo	PCM150x	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
613	Bentley	Bosch	ME7.1.1	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
649	Bmc Cummins Engines	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
3	Bmw	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
100	Bmw	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
154	Bmw	Bosch	EDC17 CP02	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
156	Bmw	Bosch	EDC17 CP09 external flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
220	Bmw	Bosch	EDC17 C41	TC1797	TF003	12 - INFINEON TRICORE BOSCH EDC17 TPROT8 BMW (TM012)	
666	Bmw	Bosch	EDC17 C41 GPT (F series)	TC1797	TF003	22 - INFINEON TRICORE BOSCH EDC17 GPT BMW	
221	Bmw	Bosch	EDC17 C45	TC1797	TF003	12 - INFINEON TRICORE BOSCH EDC17 TPROT8 BMW (TM012)	
667	Bmw	Bosch	EDC17 CP45 GPT (F series)	TC1797	TF003	22 - INFINEON TRICORE BOSCH EDC17 GPT BMW	
668	Bmw	Bosch	EDC17 CP50/EDC17 CP56 GPT (F series)	TC1797	TF003	22 - INFINEON TRICORE BOSCH EDC17 GPT BMW	
604	Bmw	Bosch	ME7.2	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
19	Bmw	Bosch	ME9	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
229	Bmw	Bosch	ME9 2xDE28F800F3	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
103	Bmw	Bosch	ME9+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
163	Bmw	Bosch	ME9+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
452	Bmw	Bosch	ME17.2 BMSX	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDDII PATCH / SBLOCCO OBDDII
171	Bmw	Bosch	MEV1746	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
215	Bmw	Bosch	MEVD17.2	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
18	Bmw	Siemens	MS45.0	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
117	Bmw	Siemens	MSS 60 - MSS 65 #L	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
116	Bmw	Siemens	MSS 60 - MSS 65 #R	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
110	Bmw	Siemens	MSV70 / MSS70	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
65	Bmw / Mini	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
148	Bmw / Mini / PSA Group	Bosch	MED17.2/MEV17.2 (ext. Flash)	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
516	Bmw / Mini / PSA Group	Bosch	MEVD17.2.7	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
485	Bmw / Yanmar	Bosch	EDC16C1-4.41	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
136	Bmw Bikes	Bosch	ME9 BMSK	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
188	Bmw Bikes	Bosch	ME9+ BMSK	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
552	Brp	Continental Siemens VDO	M3C S12XET256MAL	MC9512XS256	TF008	10 - MOTOROLA HC12 (TM010)	
536	Bugatti	Bosch	ME9.1.1	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
467	Case / New Holland	Bosch	EDC17_C49	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
124	Case (Cummins)	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
392	Caterham	MBE	958	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
385	Caterpillar	Caterpillar	Adem III (AT25640 eeprom)	MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)	
440	Caterpillar	Caterpillar	Adem III (AT25160 eeprom)	MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)	
648	Caterpillar	Caterpillar	Adem III (HWIII)	MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)	
332	Caterpillar	Caterpillar	Adem IV (561/562)	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
360	Caterpillar	Caterpillar	Adem IV (563/564 S29CD016G)	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
408	Caterpillar	Caterpillar	Adem IV (563/564 S29CD032J)	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
161	Caterpillar	Delphi	Perkins	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
323	CF Motor	Bosch	MSE3	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
409	Chery	Bosch	ME7.9.7	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
429	Chery	IAW Marelli	IAW4AC	ST10F269	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
576	Chery	Siemens	SIMK31	ST10C167	TF002	05 - SPECIAL ST10 (TM005)	
17	Chevrolet / GM Group	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
74	Chevrolet / GM Group	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
660	Chevrolet / GM Group	Bosch	EDC16C39	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
519	Chevrolet / GM Group	Bosch	EDC16C42	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
224	Chevrolet / GM Group / FCA (Fiat/Chrysler Automobiles)	Bosch	ME7.9.9	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
309	Chevrolet / GM Group	Bosch	ME9.1 / ME9.5	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
202	Chevrolet / GM Group	Continental	SIM2K	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
14	Chrysler / Jeep	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
106	Chrysler / Jeep	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
503	Chrysler / Jeep	Bosch	EDC17_C49	TC1797	TF003	15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAL (TM015)	
371	Chrysler / Jeep	Motorola	NGC4	MPC5554	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)	
372	Chrysler / Jeep	Motorola	NGC5	MPC5554	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)	
193	Cummins engines (generic)	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
406	Cummins engines (Tractor generic)	Motorola	CM871	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
565	Cummins engines (Truck generic)	Motorola	CM870	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
546	Cummins engines (Truck generic)	Continental	CM2150E	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)	
361	Daewoo / Opel GM Group	Siemens	M300 B10D	ST10C167	TF002	05 - SPECIAL ST10 (TM005)	
134	Daf Truck	Bosch	EDC7C-C1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
142	Daf Truck	Delphi	DCMI	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
509	Daf Truck / Paccar	Delphi	PCX2	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)	
506	Daf Truck	Continental	CM2150C	MPC5554	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)	
403	Daf Truck	Continental	CM2150E	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)	
125	Daf Truck	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
639	Daimler Trucks	Continental	CM2250	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)	
543	Detroit Diesel Trucks	Temic	ACM2	TC1796	TF003	14 - INFINEON TRICORE NO PSW KLINE (TM014)	
144	Deutz / Fendt (AGCO Group)	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
160	Deutz / Fendt (AGCO Group)	Bosch	EDC7U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
227	Deutz / Fendt (AGCO Group)	Bosch	EDC17_CV52	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
572	Deutz / Fendt (AGCO Group)	Bosch	EDC17_CV54	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
436	Deutz / Fendt (AGCO Group)	Bosch	EDC17_CV56	ST10C167	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
80	Dodge	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
95	Dodge	Motorola	CM848B	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
641	Dodge	Motorola	NGC5	MPC5554	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)	
473	Dodge	Siemens	SIM90T	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
635	Doosan	Bosch	EDC17_CV41	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)	
87	Ducati / MV Agusta	IAW Marelli	55M	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
341	Ducati	Continental Siemens VDO	M3C S12X256SV	MC9512XS256	TF008	10 - MOTOROLA HC12 (TM010)	
540	Ducati	Continental Siemens VDO	M3C S12XET256MAL	MC9512XS256	TF008	10 - MOTOROLA HC12 (TM010)	
653	Ducati	Melco	HIMEJI	MH8106F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)	
394	Duramax	Bosch	EDC17_CP18	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
1	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
70	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
141	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
363	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC17_CP52	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
503	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC17_C49	TC1797	TF003	15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAL (TM015)	
655	FCA (Fiat/Chrysler Automobiles)	Bosch	EDC17_C69	TC1793	TF003	15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAL (TM015)	
24	FCA (Fiat/Chrysler Automobiles)	Bosch	ME7.9.10	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
659	FCA (Fiat/Chrysler Automobiles)	Bosch	ME17.3.0	TC1724	TF003	03 - INFINEON TRICORE NO PSW (TM003)	
642	FCA (Fiat/Chrysler Automobiles)	Bosch	MED17.3.0	TC1724	TF003	15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAL (TM015)	
150	FCA (Fiat/Chrysler Automobiles)	Bosch	MED17.3.1	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDDII PATCH / SBLOCCO OBDDII
New 643	FCA (Fiat/Chrysler Automobiles)	Bosch	MED17.3.3	TC1793	TF003	15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAL (TM015)	
30	FCA (Fiat/Chrysler Automobiles)	Bosch	MED7.1.1	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
27	FCA (Fiat/Chrysler Automobiles)	Bosch	MED7.6.1	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
26	FCA (Fiat/Chrysler Automobiles)	Bosch	MED7.6.2	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
44	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	4SF / 4DF	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
380	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	4CF	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
381	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	4GF	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
63	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	5SF8 / 5SF9	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
28	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	5SFHWxxx	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
91	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	6KPB	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
247	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	7GF	MPC5534	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)	
645	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	8DF.11	MPC5553	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)	
245	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	8GF	MPC5553	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)	
243	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	8GMF	MPC5565	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)	
382	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	8F3	MPC5565	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)	
413	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	8TDF	MPC5553	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)	
85	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	MJD 6F3	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
101	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	MJD 6F3	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
8	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	MJD 6JF	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
349	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	MJD 6F3 HW04W	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
303	FCA (Fiat/Chrysler Automobiles)	IAW Marelli	MJD 8DF	MPC5565	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)	
83	FCA (Fiat/Chrysler Automobiles)	Siemens	SID 803A 5WS40320	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
38	FCA (Fiat/Chrysler Automobiles) / PSA Group	Visteon	DCU-102	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
366	Fendt (AGCO Group)	Agco	Gearbox	ST10F269	TF002	05 - SPECIAL ST10 (TM005)	
42	Ferrari / Maserati	Bosch	ME7.3.2	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
335	Ferrari	Bosch	MED9.6.1	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
121	Ford	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
197	Ford	Bosch	EDC17 CP05	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
230	Ford	Bosch	EDC17 C10	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
301	Ford	Bosch	EDC17 CP42	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
76	Ford	Bosch	ME9+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
279	Ford	Bosch	MEDG9.8	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
238	Ford	Bosch	MED17.2	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
200	Ford	Bosch	MED17.8.5	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
586	Ford	Bosch	MED17.2	TC1767	TF003	20 - INFINEON TRICORE BOSCH MEDC17 TPROT12 FORD	
618	Ford	Bosch	MED17.2.2	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
233	Ford	Delphi	DCM	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
302	Ford	Delphi	DCM3.5	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)	
343	Ford	FoMoCo	JDS0	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
393	Ford	IAW Marelli	4CF	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
464	Ford	IAW Marelli	4AFR	ST10F269	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
New 663	Ford	Siemens	EMS2205	TC1762 / TC1766	TF003	03 - INFINEON TRICORE NO PSW (TM003)	
145	Ford	Siemens	SID 206 5WS40483	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
460	Ford	Siemens	ST10C167	ST10C167	TF002	05 - SPECIAL ST10 (TM005)	
178	Ford	Siemens/Continental	SID807	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)	
511	Ford	Siemens Continental	SID807EVO	TC1797	TF003	16 - INFINEON TRICORE FOMOCO SID208/SID807 (TM016)	Patch (OBDDII Unlock)
20	Ford / Jaguar	Delphi		MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
510	Ford / Land Rover	FoMoCo Continental	SID208	TC1797	TF003	16 - INFINEON TRICORE FOMOCO SID208/SID807 (TM016)	Patch (OBDDII Unlock)
11	Ford / Mazda	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
60	Ford / PSA Group	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
66	Ford / PSA Group	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
32	Ford / PSA Group / Volvo	Siemens	SID 803 5WS40xxx	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
78	Ford / PSA Group / Volvo	Siemens	SID 803A 5WS40xxx	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
82	Ford / Volvo	Siemens	SID 206 5WS40xxx	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
31	Ford Truck	Bosch	EDC7C1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
504	Ford Truck	Continental	CM2150E	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)	
461	Freightliner / Mercedes Truck	Temic	DDEC6	TC1796	TF003	14 - INFINEON TRICORE NO PSW KLINE (TM014)	
228	GM Group / Opel	Bosch	EDC17 C18	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
7	GM Group / Opel	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
153	GM Group / Opel	Bosch	EDC17 C19	TC1792	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
192	GM Group / Opel	Bosch	ME7.6.4	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
309	GM Group / Opel / Chevrolet	Bosch	ME9.1 / ME9.5	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
225	GM Group / Opel	Bosch	ME9.6	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
465	GM Group / Opel	Delco	E83	MPC5565	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)	
466	GM Group / Opel	Delco	E37	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
458	GM Group / Opel / Chevrolet	Delphi	DCM 3.7	SH72513	TF005	07 - RENESAS SH7050 (TM007)	
520	GM Group / Opel	Delphi	DCM 3.7	SH72544R	TF005	07 - RENESAS SH7050 (TM007)	
605	GM Group / Opel	Delphi	DCM 3.7AP	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)	
253	GM Group / Opel	Denso	1.7 DTI	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
295	GM Group / Opel	Denso	1.7 DTI SH7059	SH7059	TF005	07 - RENESAS SH7050 (TM007)	
322	GM Group / Opel / Isuzu	Denso	3.0 V6 DTI	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
111	GM Group / Opel	IAW Marelli	MJD 602.A6	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
107	GM Group / Opel	IAW Marelli	MJD 602.M1 - MJD 603.S3	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
176	GM Group / Opel	IAW Marelli	MJD 602.M1 - MJD 603.S3	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
10	GM Group / Opel	IAW Marelli	MJD 6JF	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
348	GM Group / Opel / Suzuki	IAW Marelli	MJD 602.04	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
333	GM Group / Opel	Siemens	SIMTEC 76	ST10C167	TF002	05 - SPECIAL ST10 (TM005)	
84	Great Wall Motor	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDDII PATCH / SBLOCCO OBDDII
439	Great Wall Motor	Bosch	ME7.8.8	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
470	Great Wall Motor	Bosch	EDC17_C53	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
388	Great Wall Motor	Delphi	DCM 3.7	SH72513	TF005	07 - RENESAS SH7050 (TM007)	
347	Hino	Denso	896xx	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
487	Hino	Denso	895xx	SH7055	TF005	07 - RENESAS SH7050 (TM007)	
12	Honda	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
172	Honda	Bosch	EDC17_CP06	TC1792	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
213	Honda	Bosch	EDC17_CP16	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
497	Honda	Bosch	ME7.9.3	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
492	Honda	Keihin	37805-Rxx	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
617	Honda	Keihin	37820-RAH	SH7055	TF005	07 - RENESAS SH7050 (TM007)	
61	Hyundai / Kia	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
72	Hyundai / Kia	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
164	Hyundai / Kia	Bosch	EDC17_C08	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
127	Hyundai / Kia	Bosch	EDC17_CP14	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
608	Hyundai / Kia	Bosch	EDC17_C53	TC1767	TF003	19 - INFINEON TRICORE BOSCH MEDC17 TPROT10/11 HYUNDAI/KIA	
167	Hyundai / Kia	Bosch	M7.9.8	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
597	Hyundai / Kia	Bosch	ME7.9.7	ST10F275	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
339	Hyundai / Kia	Bosch	ME17.9.11	TC1762 / TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
496	Hyundai / Kia	Bosch	MED17.9.8	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
416	Hyundai / Kia	Bosch	MEG17.9.11	TC1762 / TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
549	Hyundai / Kia	Bosch	EDC17_CP14	TC1796	TF003	19 - INFINEON TRICORE BOSCH MEDC17 TPROT10/11 HYUNDAI/KIA	
550	Hyundai / Kia	Bosch	MED17.9.8/MEDG17.9.8	TC1767	TF003	19 - INFINEON TRICORE BOSCH MEDC17 TPROT10/11 HYUNDAI/KIA	
194	Hyundai / Kia	Continental	SIM2K	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
387	Hyundai / Kia	Delphi	DCM 3.7	SH72513	TF005	07 - RENESAS SH7050 (TM007)	
317	Hyundai / Kia	Kefico	MH8305H	MH8305H	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
351	Hyundai / Kia	Kefico	KTS3	MH8X02F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
575	Hyundai / Kia	Mitsubishi	39106-3945x	MH82XF	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
352	Hyundai / Kia	Siemens	SIMK43 5WY1xxxx	ST10C167	TF002	05 - SPECIAL ST10 (TM005)	
353	Hyundai / Kia	Siemens	SIMK43 5WY44xxx #L	ST10C167	TF002	05 - SPECIAL ST10 (TM005)	
354	Hyundai / Kia	Siemens	SIMK43 5WY44xxx #R	ST10C167	TF002	05 - SPECIAL ST10 (TM005)	
367	Hyundai / Kia	Siemens	SIM2K-47 5WY4Cxxx #L	ST10C167	TF002	05 - SPECIAL ST10 (TM005)	
368	Hyundai / Kia	Siemens	SIM2K-47 5WY4Cxxx #R	ST10C167	TF002	05 - SPECIAL ST10 (TM005)	
521	Hyundai / Kia	Siemens Continental	SIM2K	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
169	Hyundai / Kia (Cummins)	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
112	Hyundai / Kia / Ssangyong	Delphi	DCM3.2	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
621	International Truck	Bosch	EDC7UC31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
400	International Truck (Cummins)	Motorola	CM870	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
401	International Truck (Cummins)	Motorola	CM871 / CM876	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
79	Isuzu / Chevrolet	Delphi		MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
322	Isuzu / GM Group / Opel	Denso	3.0 V6 DTI	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
412	Isuzu	Denso	25841077	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
313	Isuzu	Transtron		SH7055	TF005	07 - RENESAS SH7050 (TM007)	
430	Isuzu	Transtron	4Jxx	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
130	Iveco	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
140	Iveco	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
206	Iveco	Bosch	EDC17	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
432	Iveco	Bosch	EDC17_C49	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
633	Iveco	Bosch	EDC17_CV41	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)	
568	Iveco	IAW Marelli	5SF4	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
129	Iveco / New Holland	Bosch	EDC7C1-C2	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
137	Iveco / New Holland	Bosch	EDC7U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
346	Jaguar	Denso	MB079700	SH7055	TF005	07 - RENESAS SH7050 (TM007)	
422	Jaguar	Denso	MB279700-9xxx	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
498	Jaguar / Land Rover	Denso	P5.0SC	SH7059	TF005	07 - RENESAS SH7050 (TM007)	
105	Jaguar	Siemens	SID 201 - SID 204 5WS40xxx	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
402	JCB	Bosch	EDC17_CV54	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
593	JCB	Continental	CM2250	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)	
191	JCB Fastrack	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
256	Jeep	Bosch	EDC17_CP27	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
77	Jeep / Mitsubishi	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
503	Jeep / Chrysler / FCA (Fiat/Chrysler Automobiles)	Bosch	EDC17_C49	TC1797	TF003	15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAL (TM015)	
123	John Deere	Phoenix	L14	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
236	John Deere	Phoenix	L16	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
190	John Deere	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
462	John Deere	Phoenix	L11	ST10F168	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
463	John Deere	Phoenix	L4	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
457	John Deere	Siemens	UIC2	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
522	Kawasaki	Denso	21775-0046	SH7054	TF005	07 - RENESAS SH7050	
532	Kawasaki	Denso	21775-0097	SH7054	TF005	07 - RENESAS SH7050	
620	Kawasaki	Denso	21775-07XX	SH7054	TF005	07 - RENESAS SH7050	
561	Kawasaki	Denso	21775-109X	SH7054	TF005	07 - RENESAS SH7050	
525	Kawasaki	Denso	21175-0220	M32R196	TF009	17 - RENESAS M32R (TM017)	
652	Kawasaki	Denso	21175-08XX	M32R196	TF009	17 - RENESAS M32R (TM017)	
455	Kawasaki	Melco	ULTRA 300X	MH8106F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
530	Kawasaki	Melco	21175-3732	MH7203	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
285	Kawasaki	Mitsubishi	JetSki Ultra 250	MH82XF	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
300	Kawasaki	Mitsubishi	ZRX1200	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDDI PATCH / SBLOCCO OBDDI
484	Kawasaki	Mitsubishi	ZX10R	MH82XXF	TF006	08 - MITSUBISHI MH7xxx/MH8xxx	
488	Kawasaki	Mitsubishi	ZX10R MY07	MH82XXF	TF006	08 - MITSUBISHI MH7xxx/MH8xxx	
637	Kawasaki	Mitsubishi	Z1175-033X	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx	
541	Khodro/Saipa	Continental	SIM2K-34 5WY5Kxxx	ST10C167	TF002	05 - SPECIAL ST10 (TM005)	
379	King Long	Continental	CM2150E	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)	
438	Komatsu	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
418	Ktm	Bosch	M17.8.7	TC1762 / TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
578	Kubota	Denso	275800-7221	SH7058	TF005	07 - RENESAS SH7050	
584	Kubota	Denso	275700-1201	SH7058	TF005	07 - RENESAS SH7050	
469	Lamborghini	Campi	Campi	MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)	
376	Lada / UAZ	Bosch	M7.9.7	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
428	Lada / UAZ	Bosch	ME17.9.7	TC1762 / TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
120	Land Rover	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
177	Land Rover	Bosch	EDC17_CP11	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
235	Land Rover	Bosch	EDC17_CP42	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
483	Land Rover	Denso	MB279700-94xx	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
510	Land Rover / Ford	FoMoCo Continental	SID208	TC1797	TF003	16 - INFINEON TRICORE FOMOCO SID208/SID807 (TM016)	
98	Land Rover	Siemens	SID 201 - SID 204 5WS40xxx	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
115	Land Rover	Siemens	SID 203 5WS40371	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
384	Land Rover	Siemens	SID 204 5WS40xxx	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
37	Land Rover	Visteon	DCU-106	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
498	Land Rover / Jaguar	Denso	P5.05C	SH7059	TF005	07 - RENESAS SH7050 (TM007)	
310	LDV	Bosch	EDC16+ C39	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
567	Lindner Perkins	Bosch	EDC17_C49	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
287	Lotus	Efi	Efi	MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)	
306	Lotus	Efi	Efi	MC68300	TF007	09 - MOTOROLA MC68xxx (TM009)	
437	Lotus	Efi	T4E	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
507	Lotus	Efi	T6E	MPC5534	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)	
447	LTI	Bosch	EDC16+ C39	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
453	Mack	Bosch	EDC7U/U1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
21	Mahindra	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
495	Mahindra	Bosch	EDC17_C55	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
558	Mahindra	Bosch	EDC17_C53	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
135	Man Truck	Bosch	EDC7C3	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
139	Man Truck	Bosch	EDC7C32	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
538	Man Latin America / Volkswagen Trucks	Continental	CM2150E	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)	
226	Maserati	Bosch	ME911	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
596	Maserati	Bosch	EDC17_C79	TC1797	TF003	15 - INFINEON TRICORE BOSCH EDC17 TPROT11 FAL (TM015)	
270	Massey Ferguson / McCormick / Caterpillar	Perkins	Caterpillar Tier2	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
651	Maz Trucks	Bosch	EDC7UC31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
395	Mazda	Denso	N3J1	SH7055	TF005	07 - RENESAS SH7050 (TM007)	
263	Mazda	Denso	R2AX	SH7059	TF005	07 - RENESAS SH7050 (TM007)	
278	Mazda	Denso	RF7K	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
277	Mazda	Denso	RF8G	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
321	Mazda	Denso	L831	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
327	Mazda	Denso	R2AA	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
344	Mazda	Denso	ZJ77	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
454	Mazda	Denso	ZYE9	SH7059	TF005	07 - RENESAS SH7050 (TM007)	
476	Mazda	Denso	L3T4	SH7055	TF005	07 - RENESAS SH7050 (TM007)	
518	Mazda	Denso	L3TA	SH7055	TF005	07 - RENESAS SH7050 (TM007)	
373	Mazda	Mitsubishi	E6T5x	MH8105F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)	
475	Mazda	Mitsubishi	FPV1EA	MH7203	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)	
345	Mazda	Mitsubishi	L3B1	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)	
517	Mazda	Mitsubishi	E6T540xxxx	MH8105F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)	
603	Mazda	Mitsubishi	E6T58xxx	MH8106F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)	
4	Mercedes	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
71	Mercedes	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
97	Mercedes	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
114	Mercedes	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
222	Mercedes	Bosch	EDC17_C01	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
231	Mercedes	Bosch	EDC17_C43	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
157	Mercedes	Bosch	EDC17_CP01	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
155	Mercedes	Bosch	EDC17_CP10	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
182	Mercedes	Bosch	EDC17_CP10	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
273	Mercedes	Bosch	EDC17_CP10	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
338	Mercedes	Bosch	EDC17_CP10	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
365	Mercedes	Bosch	EDC17_CP46	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
622	Mercedes	Bosch	ME2.8	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
102	Mercedes	Bosch	ME9.7	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
204	Mercedes	Bosch	ME9.7	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
249	Mercedes	Bosch	MED17.1	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
514	Mercedes	Bosch	MED17.7.8	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
248	Mercedes	Delphi	CRD2.10	MPC5566	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)	
119	Mercedes	Delphi	DCM3.2	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
175	Mercedes	Siemens	SIM 266	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
500	Mercedes	Siemens	SIM 266 (ex flash S29CD0321)	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
580	Mercedes	Siemens	EGS52	ST10C167	TF002	05 - SPECIAL ST10 (TM005)	
581	Mercedes	Siemens	EGS53	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDDII PATCH / SBLOCCO OBDDII
461	Mercedes Truck / Freightliner	Temic	DDEC6	TC1796	TF003	14 - INFINEON TRICORE NO PSW KLINE (TM014)	
542	Mercedes Truck	Continental	HDEP	TC1796	TF003	14 - INFINEON TRICORE NO PSW KLINE (TM014)	
189	Mercury Marine	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
132	Mercury Marine	Motorola	ECM555	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
36	Mercury Marine	Motorola	PCM0308	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
35	Mercury Marine	Motorola	PCM0702	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
33	Mercury Marine	Motorola	ECM04xx	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
34	Mercury Marine	Motorola	PCMBE0101	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
90	Mercury Marine	Motorola	ECM070xx	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
441	Mercury Marine	Motorola	PCM08xx	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
442	Mercury Marine	Motorola	ECM0501	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
419	MG	Bosch	ME7.9.71	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
152	Mini	Bosch	MED172/MEV172 (irom)	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
237	Mini	Bosch	MEV17.2.2	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
208	Mini	Bosch	MEVD17.2.2	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
573	Mitsubishi	Bosch	ME7.7.1	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
43	Mitsubishi	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
170	Mitsubishi	Bosch	EDC17 CP15 (xrom)	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
640	Mitsubishi	Bosch	EDC17 C49	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
588	Mitsubishi	Bosch	EDC17 CP52	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
232	Mitsubishi	IAW Marelli	4AM	ST10F269	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
337	Mitsubishi	IAW Marelli	4CM	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
423	Mitsubishi	IAW Marelli	4GM	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
444	Mitsubishi	IAW Marelli	4DM	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
589	Mitsubishi	IAW Marelli	4GT	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
99	Mitsubishi / Smart	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
265	Mitsubishi	Denso	(4D56 engine)	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
283	Mitsubishi	Denso	EVOX	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
319	Mitsubishi	Denso	RA6	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
324	Mitsubishi	Denso	RA6 4N13	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
417	Mitsubishi	Denso	RA6 4D56	SH7059	TF005	07 - RENESAS SH7050 (TM007)	
601	Mitsubishi	Denso	6M60	SH7055	TF005	07 - RENESAS SH7050 (TM007)	
548	Mitsubishi	IAW Marelli	IAW4DM CR47	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
350	Mitsubishi	Melco	G1Tx	MH802F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
570	Mitsubishi	Mitsubishi	E2T1xxx	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
449	Mitsubishi	Mitsubishi	E2T7xxx MH7203	MH7203	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
609	Mitsubishi	Mitsubishi	E2T79xxx	MH8306F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
479	Mitsubishi	Mitsubishi	E6T310xx	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
493	Mitsubishi	Mitsubishi	E6T310xx	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
585	Mitsubishi	Mitsubishi	E6T36xxx	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
474	Mitsubishi	Mitsubishi	E6T38xxx	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
482	Mitsubishi	Mitsubishi	E6T41xxx	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
602	Mitsubishi	Mitsubishi	E6T44xxx	MH8304F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
410	Mitsubishi	Mitsubishi	E6T47xxx	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
391	Mitsubishi	Mitsubishi	E6T49xxx	MH8304F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
583	Mitsubishi	Mitsubishi	E6T74xxx	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
426	Mitsubishi	Mitsubishi	E6T76xxx	MH8106F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
328	Mitsubishi	Mitsubishi	E6T7x	MH8106F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
329	Mitsubishi (Colt 1.5 asp.)	Mitsubishi	MH7x/MH8x	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
255	Mitsubishi (Colt 1.5 turbo)	Mitsubishi	MH7x/MH8x	MH8203F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
261	Mitsubishi (Lancer EVO IX)	Mitsubishi	MH7x/MH8x	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
259	Mitsubishi (Lancer EVO VI)	Mitsubishi	MH7x/MH8x	MH7202F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
260	Mitsubishi (Lancer EVO VII/VIII)	Mitsubishi	MH7x/MH8x	MH7202F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
297	Mitsubishi (Pajero 3.2 DI-D)	Mitsubishi	MH7x/MH8x	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
318	Mitsubishi	Mitsubishi	3.2 D	MH7203	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
547	Moto Guzzi	IAW Marelli	IAW7SM	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
217	MV Agusta	IAW Marelli	7BM	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
143	New Holland	Bosch	EDC16+ C39/UC40	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
467	New Holland / Case	Bosch	EDC17 C49	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
129	New Holland / Iveco	Bosch	EDC7C1-C2	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
137	New Holland / Iveco	Bosch	EDC7U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
478	Nissan	Bosch	EDC16CP42	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
657	Nissan	Bosch	EDC17 C45	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
264	Nissan	Denso	D3	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
294	Nissan	Denso	1H	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
314	Nissan	Denso	HP	SH7059	TF005	07 - RENESAS SH7050 (TM007)	
315	Nissan	Denso	HWII	SH7055	TF005	07 - RENESAS SH7050 (TM007)	
445	Nissan	Hitachi	A56-B7x	SH7055	TF005	07 - RENESAS SH7050 (TM007)	
450	Nissan	Hitachi	A56-C1x	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
481	Nissan	Hitachi	BED301-000	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
448	Nissan	Hitachi	DEA030-2xx	SH7059	TF005	07 - RENESAS SH7050 (TM007)	
296	Nissan	Hitachi	HPNGV	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
396	Nissan	Hitachi	HPNGV SH7059	SH7059	TF005	07 - RENESAS SH7050 (TM007)	
298	Nissan	Hitachi	HW 1	SH7055	TF005	07 - RENESAS SH7050 (TM007)	
299	Nissan	Hitachi	HW 4	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
527	Nissan	Hitachi	L80-2013	SH7055	TF005	07 - RENESAS SH7050 (TM007)	
502	Nissan	Hitachi	MEC-100-xxx	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
414	Nissan	Hitachi	MEC-107	SH7059	TF005	07 - RENESAS SH7050 (TM007)	

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDDII PATCH / SBLOCCO OBDDII
494	Nissan	Hitachi	MEC-23-xxx	SH7055	TF005	07 - RENESAS SH7050 (TM007)	
451	Nissan	Hitachi	MEC-30-07x	SH7055	TF005	07 - RENESAS SH7050 (TM007)	
600	Nissan	Hitachi	MEC-35	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
650	Nissan	Hitachi	MEC-37-3xx	SH7054	TF005	07 - RENESAS SH7050 (TM007)	
415	Nissan	Hitachi	MEC-73-xxx	SH7059	TF005	07 - RENESAS SH7050 (TM007)	
606	Nissan	Hitachi	MEC-78-xxx	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
501	Nissan	Hitachi	MEC-90-xxx	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
587	Nissan	Hitachi	MEC-940-xxx	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
486	Nissan Truck (Cummins engine)	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
431	Peterbilt Truck (Cummins engine)	Motorola	CM870	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
377	Piaggio	Bosch	EDC17_C08	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
56	Polaris	Bosch	M7.4.4	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
57	Polaris	Bosch	ME7.4.4	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
282	Polaris	Bosch	ME7.9.7	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
307	Polaris	Bosch	M17.8.7	TC1762	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
240	Porsche	Bosch	ME7.2	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
242	Porsche	Bosch	ME7.8	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
41	Porsche	Bosch	ME7.8.1	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
40	Porsche	Bosch	ME7.8.2	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
159	Porsche	Bosch	ME7.8.2 min	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
39	Porsche	Siemens/Continental	VDO SDI3/SDI4	TC1796	TF003	03 - INFINEON TRICORE NO PSW (TM003)	
272	Porsche	Siemens/Continental	VDO SDI6	TC1796	TF003	11 - INFINEON TRICORE SIEMENS SDI6 PORSCHE (TM011)	
108	Porsche / VAG (VW Group)	Bosch	MED9.1 FSI - MED9.1.1 FSI	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
534	Proton	Siemens VDO	PW5XX	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
535	Proton	Siemens VDO	PW8XX	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
5	PSA Group	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
118	PSA Group	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
198	PSA Group	Bosch	EDC17 CP10	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
219	PSA Group	Bosch	EDC17_C10	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
312	PSA Group	Bosch	EDC17 CP42	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
397	PSA Group	Bosch	ME7.4.4	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
25	PSA Group	Bosch	ME7.4.5	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
569	PSA Group	Bosch	ME7.4.6	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
47	PSA Group	Bosch	ME7.4.9	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
196	PSA Group	Bosch	MED17.4/MEV17.4	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
209	PSA Group	Bosch	MED17.4/MEV17.4 (xrom)	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
305	PSA Group	Bosch	MED17.4/MEV17.4 (irom)	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
216	PSA Group	Bosch	MEVD17.4.2	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
286	PSA Group	Bosch	MEV17.4.2	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
551	PSA Group	Bosch	M7.4.4	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
257	PSA Group	Delphi	DCM3.4	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
362	PSA Group	Delphi	DCM3.4	SH7059	TF005	07 - RENESAS SH7050 (TM007)	
244	PSA Group	Delphi	DCM3.5	MPC556	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)	
55	PSA Group	Delphi	DDCR	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
45	PSA Group	IAW Marelli	6LP1.49	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
46	PSA Group	IAW Marelli	6LPC.102	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
599	PSA Group	Siemens	S2000	ST10C167	TF002	05 - SPECIAL ST10 (TM005)	
104	PSA Group	Siemens	SID 201 5WS40xxx	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
443	PSA Group	Siemens	SID 801	ST10C167	TF002	05 - SPECIAL ST10 (TM005)	
320	PSA Group	Siemens/Continental	SID 807 (irom)	TC1797	TF003	03 - INFINEON TRICORE NO PSW (TM003)	
359	PSA Group	Siemens/Continental	SID 807 (xrom)	TC1796	TF003	03 - INFINEON TRICORE NO PSW (TM003)	
122	PSA Group	Valeo Johnson	J34P	ST10F273	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
211	PSA Group	Valeo Johnson	J34P	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
491	PSA Group	Valeo Johnson	J34P HW II	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
133	Renault Group	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
6	Renault Group	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
29	Renault Group	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
62	Renault Group	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
69	Renault Group	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
223	Renault Group	Bosch	EDC16C36	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
234	Renault Group	Bosch	EDC16CP33	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
201	Renault Group	Bosch	EDC17_C11	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
181	Renault Group	Bosch	EDC17 CP19	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
456	Renault Group	Bosch	EDC17 CP58	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
258	Renault Group	Delphi	DCM3.4	SH7059	TF005	07 - RENESAS SH7050 (TM007)	
571	Renault Group	Hitachi	MEC800	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
88	Renault Group	Sagem	S2000RPM	ST10C167	TF002	05 - SPECIAL ST10 (TM005)	
250	Renault Group	Sagem	S3000	SH7055	TF005	07 - RENESAS SH7050 (TM007)	
210	Renault Group	Siemens	EMS3110	TC1766	TF003	03 - INFINEON TRICORE NO PSW (TM003)	
81	Renault Group	Siemens	SID 301	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
205	Renault Group	Siemens	SID 305	TC1766	TF003	03 - INFINEON TRICORE NO PSW (TM003)	
252	Renault Group	Siemens	SIM32	SH7055	TF005	07 - RENESAS SH7050 (TM007)	
336	Renault Group	Siemens	SIRIUS 32	ST10C167	TF002	05 - SPECIAL ST10 (TM005)	
471	Renault Group	Siemens	SIRIUS 34	ST10C167	TF002	05 - SPECIAL ST10 (TM005)	
251	Renault Group	Valeo	V40	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
280	Renault Group	Valeo	S3000	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
398	Renault Group / Nissan	Bosch	EDC17_C42	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
292	Renault Group / Samsung	Hitachi	DA A56-Y8x	SH7055	TF005	07 - RENESAS SH7050 (TM007)	

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDDII PATCH / SBLOCCO OBDDII
138	Renault Truck / Volvo Truck	TRW	EMS2	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
180	Rotax (Sea Doo Acqua Scooter)	Bosch	ME17.8.5	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
330	Rotax	Siemens VDO	MSE 3.7	ST10F269	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
411	Rotax	Siemens VDO	MSE 3.7 R/H3	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
New 654	Same	Bosch	EDC17 C53	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
131	Scania Truck	Motorola	EDCS6	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
590	Scania Truck	Continental	EMS S7	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
594	Scania Truck	Continental	EMS S8	MPC556	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)	
23	Smart	Bosch	ME7.7.0	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
480	Smart	Mitsubishi	G2T601x Gearbox	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx	
22	Ssangyong	Delphi		MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
459	Ssangyong	Delphi	DCM 3.7	SH72513	TF005	07 - RENESAS SH7050 (TM007)	
524	Ssangyong	Delphi	DCM 3.7	SH72544R	TF005	07 - RENESAS SH7050 (TM007)	
276	Subaru	Denso	DT	SH7059	TF005	07 - RENESAS SH7050 (TM007)	
275	Subaru	Denso	KS	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
281	Subaru	Denso	CJ	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
375	Subaru	Denso	DM	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
564	Subaru	Denso	112200-8481	SH7055	TF005	07 - RENESAS SH7050 (TM007)	
644	Subaru	Hitachi	DEF002-XXX	SH7059	TF005	07 - RENESAS SH7050 (TM007)	
16	Suzuki	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
212	Suzuki	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
446	Suzuki	Bosch	EDC16+ C39	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
340	Suzuki	Bosch	ME17.8.XX	TC1762 / TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
434	Suzuki	Bosch	ME17.8.XX	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
262	Suzuki	Denso	1.3 MT	SH7055	TF005	07 - RENESAS SH7050 (TM007)	
316	Suzuki	Denso	1.6 MT	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
331	Suzuki	Denso	076Jx	SH7055	TF005	07 - RENESAS SH7050 (TM007)	
370	Suzuki	Denso	057L1	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
523	Suzuki	Denso	32920-21Hxxx	M32R196	TF009	17 - RENESAS M32R (TM017)	
526	Suzuki	Denso	32920-30G00	SH7054	TF005	07 - RENESAS SH7050 (TM007)	
528	Suzuki	Denso	32920-08J11	M32R196	TF009	17 - RENESAS M32R (TM017)	
533	Suzuki	Denso	32920-01H000	SH7054	TF005	07 - RENESAS SH7050 (TM007)	
9	Suzuki	IAW Marelli	UZ13DT	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
348	Suzuki / GM Group / Opel	IAW Marelli	MJD 602.04	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
364	Suzuki	IAW Marelli	8DS	MPC5565	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)	
355	Suzuki	Mitsubishi	E6T900 M0	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)	
489	Suzuki	Mitsubishi	E6T13xxx	MH7203	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)	
369	Suzuki	Mitsubishi	E6T172	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)	
616	Suzuki	Mitsubishi	33920-93J40	MH5xxxF	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)	
254	Suzuki Outboard	Melco		MH7203F	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)	
477	Suzuki Outboard	Melco		MH7202	TF006	08 - MITSUBISHI MH7xxx/MH8xxx (TM008)	
15	Tata	Delphi		MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
636	Tata	IAW Marelli	MJD 602	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
404	Tata Trucks (Cummins)	Motorola	CM876	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
13	Toyota	Bosch	EDC16	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
195	Toyota	Bosch	EDC17 CP07	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
356	Toyota	Bosch	ME7.9.5	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
54	Toyota	Bosch	ME7.9.51	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
2	VAG (VW Group)	Bosch	EDC16 U2.1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	Patch (OBDDII Unlock)
67	VAG (VW Group)	Bosch	EDC16+ U34	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	Patch (OBDDII Unlock)
96	VAG (VW Group)	Bosch	EDC16+ CP	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	Patch (OBDDII Unlock)
109	VAG (VW Group)	Bosch	EDC16+ CP	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	Patch (OBDDII Unlock)
199	VAG (VW Group)	Bosch	EDC17 C46	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	Patch (OBDDII Unlock)
269	VAG (VW Group)	Bosch	EDC17 C46	TC1767	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)	Patch (OBDDII Unlock)
126	VAG (VW Group)	Bosch	EDC17 CP04	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
146	VAG (VW Group)	Bosch	EDC17 CP14 external flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	Patch (OBDDII Unlock)
151	VAG (VW Group)	Bosch	EDC17 CP14 internal flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	Patch (OBDDII Unlock)
166	VAG (VW Group)	Bosch	EDC17 CP14 USA ext. flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	Patch (OBDDII Unlock)
425	VAG (VW Group)	Bosch	EDC17 CP14	TC1796	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)	Patch (OBDDII Unlock)
165	VAG (VW Group)	Bosch	EDC17 CP20 external flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
187	VAG (VW Group)	Bosch	EDC17 CP20 internal flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
427	VAG (VW Group)	Bosch	EDC17 CP20 (irom)	TC1796	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)	
162	VAG (VW Group)	Bosch	EDC17 CP24 external flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
203	VAG (VW Group)	Bosch	EDC17 CP44	TC1797	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
268	VAG (VW Group)	Bosch	EDC17 CP44	TC1797	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)	
149	VAG (VW Group)	Bosch	EDC17 U01	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
207	VAG (VW Group)	Bosch	EDC17 U05 external flash	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
420	VAG (VW Group)	Bosch	EDC17 C54	TC1797	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)	
50	VAG (VW Group)	Bosch	ME7.1.1	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
51	VAG (VW Group)	Bosch	ME7.1.1	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
52	VAG (VW Group)	Bosch	ME7.1.1	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
48	VAG (VW Group)	Bosch	ME7.5	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
53	VAG (VW Group)	Bosch	ME7.5	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
49	VAG (VW Group)	Bosch	ME7.5.10	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
186	VAG (VW Group)	Bosch	ME7.5.20 - ME7.5.30	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
168	VAG (VW Group)	Bosch	MED17.1 (irom)	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
218	VAG (VW Group)	Bosch	MED17.1 (xrom)	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
293	VAG (VW Group)	Bosch	MED17.1	TC1796	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)	

PLUGIN ID	VEHICLE MANUFACTURER / COSTRUTTORE	ECU BRAND / MARCA ECU	ECU MODEL / MODELLO ECU	CPU (PROCESSOR) / CPU (PROCESSORE)	CPU GROUP / GRUPPO CPU	CPU APPLICATION (SPEC.) / FAMIGLIA CPU (SPEC.)	OBDDII PATCH / SBLOCCO OBDDII
266	VAG (VW Group)	Bosch	MED17.1.1	TC1796	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)	
378	VAG (VW Group)	Bosch	MED17.1.6	TC1797	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)	
128	VAG (VW Group)	Bosch	MED17.5	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
472	VAG (VW Group)	Bosch	MED17.5	TC1767	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)	
147	VAG (VW Group)	Bosch	MED17.5.1	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
267	VAG (VW Group)	Bosch	MED17.5.1	TC1766	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)	
334	VAG (VW Group)	Bosch	MED17.5.2 (Irom)	TC1767	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)	
358	VAG (VW Group)	Bosch	MED17.5.6	TC1767	TF003	13 - INFINEON TRICORE BOSCH MEDC17 TPROT8/10 VAG (TM013)	
435	VAG (VW Group)	Bosch	MED17.5.10	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
179	VAG (VW Group)	Bosch	MED17.5.20	TC1766	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
64	VAG (VW Group)	Bosch	MED9.1/MED9.5/MED9.5.10	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
539	VAG (VW Group)	Bosch	ME7.1.1	ST10F275 / ST10F276	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
183	VAG (VW Group)	IAW Marelli	4AV	ST10F269	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
183	VAG (VW Group)	IAW Marelli	4BV	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
185	VAG (VW Group)	IAW Marelli	4HV	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
173	VAG (VW Group)	IAW Marelli	4TV	ST10F280	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
374	VAG (VW Group)	IAW Marelli	4GV	ST10F296	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
390	VAG (VW Group)	IAW Marelli	4AF	ST10F269	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
75	VAG (VW Group)	Siemens VDO	SIMOS 5WP4 PPD1.x	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
174	VAG (VW Group)	Siemens VDO	SIMOS 6.2 6.3	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
214	VAG (VW Group)	Siemens VDO	SIMOS 6.2 6.3	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
512	VAG (VW Group)	Siemens VDO	SIMOS 8.x	ST95640	TF003	18 - INFINEON TRICORE SIEMENS PCR2.1/SIMOS8.xx VAG (TM018)	Patch (OBDDII Unlock)
513	VAG (VW Group)	Siemens VDO	PCR2.1	ST95640	TF003	18 - INFINEON TRICORE SIEMENS PCR2.1/SIMOS8.xx VAG (TM018)	Patch (OBDDII Unlock)
89	Valtra Sisu (AGCO Group)	Bosch	EDC7U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
58	Volkswagen Truck	Bosch	EDC7C1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
342	Volkswagen Truck	Bosch	EDC16C8	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
93	Volkswagen Truck (Cummins)	Motorola	CM850	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
68	Volvo	Bosch	EDC16+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
113	Volvo	Bosch	EDC16+	MPC563 / MPC564	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
158	Volvo	Bosch	EDC17 CP22	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
325	Volvo	Bosch	ME7	ST10C167	TF002	02 - STMICROELECTRONICS ST10 (TM002)	
73	Volvo	Bosch	ME9+	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
326	Volvo	Denso	2.4	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
421	Volvo	Denso	079700-9xxx	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
499	Volvo	Denso	HP.2	SH7055	TF005	07 - RENESAS SH7050 (TM007)	
399	Volvo Penta	Bosch	EDC17 CP22	TC1796	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	
59	Volvo Truck / Volvo Penta	Bosch	EDC7C1	MPC555 / MPC556	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
138	Volvo Truck / Renault Truck	TRW Motorola	EMS2	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
246	Volvo Truck / Renault Truck	TRW Motorola	EMS2 (EURO4/EURO5 version)	MPC554	TF004	06 - NEXUS MOTOROLA MPC55XX (TM006)	
357	Volvo Power Generator	TRW Motorola	EMS2	MPC565 / MPC566	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
433	Weichai Truck (Weichai engines)	Bosch	EDC7 UC31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
612	XCMG	Bosch	EDC7 U31	MPC561 / MPC562	TF001	01 - MOTOROLA MPC55X/MPC56X (TM001)	
559	Yale	Sagem	S3000	SH7055	TF005	07 - RENESAS SH7050 (TM007)	
557	Suzuki	Denso	3C3/2C0-8591A-XX	SH7054	TF005	07 - RENESAS SH7050 (TM007)	
646	Yamaha	Denso	1RC-8591A-XX	SH7058	TF005	07 - RENESAS SH7050 (TM007)	
574	Yamaha	Melco	F8T9487x	MH7203	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
284	Yamaha	Mitsubishi	FX-SHO	MH8305F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
664	Yamaha	Mitsubishi	F8T84475	MH8102F	TF006	08 - MITSUBISHI MH7xxx/MH8xxxx (TM008)	
656	Yanmar	Bosch	EDC17 CV54	TC1767	TF003	04 - INFINEON TRICORE BOSCH MEDC17 TPROT2/4/7 (TM004)	